



Scotch-Weld™

Low-Odor Acrylic Adhesives

DP810 • DP810 NS

Technical Data

June, 2004

Product Description 3M™ Scotch-Weld™ Low-Odor Acrylic Adhesive DP810 and DP810 NS are two-part, 1:1 mix ratio, toughened structural adhesives with less odor than most acrylic adhesives. These adhesives have excellent shear and peel strength along with good impact resistance and durability. They can quickly bond to most metals, ceramics, rubbers, plastics and wood with minimal surface preparation.

- Features**
- Tough, durable bonds
 - Minimal surface prep
 - 10 minute time to handling strength
 - Bonds stainless steel
 - Low-odor acrylic adhesive
 - 10 minute worklife
 - 1:1 mix ratio
 - Excellent shear and peel strength

Typical Uncured Physical Properties

Note: The following technical information and data should be considered representative or typical only and should not be used for specification purposes.

Property		Scotch-Weld DP810	Scotch-Weld DP810 NS
Color	Base (B) Accelerator (A)	Green White	Blue/Green White
Lbs./gal.	Base (B) Accelerator (A)	8.7 - 9.1 8.7 - 9.1	8.8 - 9.2 8.7 - 9.1
Viscosity (cps)^(*)	Base (B) Accelerator (A)	18,000 - 22,000 18,000 - 22,000	90,000 - 95,000 95,000 - 100,000
Base Resin	Base (B) Accelerator (A)	Acrylic Acrylic	Acrylic Acrylic
Mix Ratio	(Volume) (Weight)	1:1 1:1	1:1 1:1
Time to Handling Strength (50 psi)		10 minutes	10 minutes
Full Cure @ 73°F (23°C)		8 - 24 hours	8 - 24 hours
Worklife @ 73°F (23°C)		10 minutes	10 minutes

(*) Viscosity obtained by Brookfield, DV-II, #7 Spindle, 20 rpm at 75°F (24°C).

Scotch-Weld™

Low-Odor Acrylic Adhesives

DP810 • DP810 NS

Typical Performance Characteristics

Note: The following technical information and data should be considered representative or typical only and should not be used for specification purposes.

Overlap Shear Strength^(*), tested @ 73°F (23°C)

	3M™ Scotch-Weld™ Low-Odor Acrylic Adhesive DP810	3M™ Scotch-Weld™ Low-Odor Acrylic Adhesive DP810 NS
Substrate	OLS (psi)	OLS (psi)
Etched Aluminum	4200 CF	4200 CF
Abraded Aluminum	3900 CF	3850 CF
Bare Aluminum	3800 CF	4100 CF
CRS	3100 CF	3500 CF
Oily CRS	3450 CF	3500 CF
Stainless Steel	3400 CF	3400 CF
Green FRP	3800 CF	1900 CF
Acrylic	1100 SF	800 SF
PVC	1000 SF	1000 SF
Polycarbonate	850 MM	500 MM
ABS	600 MM	650 MM

(*) Overlap Shear Test Method: overlap shear test for adhesion determined in accordance to ASTM D1002-72, sample dimensions were 1" x 4" x 1/8", with a 1/2 square inch area of overlap, bonded to themselves unless otherwise noted, allowed to cure for at least 6 hours at 75°F (24°C) before testing. Data was collected using a Sintech 5GL Mechanical Tester with a 2000# or 5000# load cell. Test rate was 0.1"/minute. Strength determined at 75°F (24°C) unless otherwise noted.

Overlap Shear Strength psi, tested @ Temperature

Temperature	Scotch-Weld DP810	Scotch-Weld DP810 NS
-20°F (-29°C)	1750 AF/MM	1600 AF
75°F (24°C)	3650 CF	4000 CF
120°F (49°C)	2000 CF	2350 CF
180°F (82°C)	550 CF	500 CF

T-Peel Strength (piw)^(*), tested @ 73°F (23°C)

Substrate	Scotch-Weld DP810	Scotch-Weld DP810 NS
Etched Al	30	23

(*) Peel tests (ASTM D1876-61T) on FPL etched, 0.032" gauge aluminum, with a .017" bondline thickness. Jaw separation rate 20"/min. All bonds were allowed to cure for at least 6 hours at 75°F (24°C) before testing.

SF = Substrate Failure/Break
 CF = Cohesive Failure
 AF = Adhesive Failure
 MM = Mixed (Mode of AF and CF)

Scotch-Weld™
Low-Odor Acrylic Adhesives
 DP810 • DP810 NS

Environmental Resistance^(*)

Note: The following technical information and data should be considered representative or typical only and should not be used for specification purposes.

Overlap Shear Strength (psi), tested @ 73°F (23°C)

Condition	Time	3M™ Scotch-Weld™ Low-Odor Acrylic Adhesive DP810	3M™ Scotch-Weld™ Low-Odor Acrylic Adhesive DP810 NS
Control	14 Days	3750 CF	3800 CF
160°F (71°C)/100% RH	14 Days	1500 MM	1250 AF
160°F (71°C)/Soak	14 Days	1750 MM	1450 AF
20% Bleach	14 Days	3450 CF	3750 CF
IPA	14 Days	3150 CF	3450 CF
50% Antifreeze	14 Days	3850 CF	4000 CF
Gasoline	14 Days	2550 CF	3150 CF
Diesel Fuel	14 Days	4000 CF	4050 CF
Toluene	14 Days	2650 CF	3400 CF
MEK	14 Days	50 CF	2100 CF
Acetone	14 Days	75 CF	900 CF

(*) Environmental tests were conducted by immersing bonded coupons prepared in accordance to description in footnote 2.

CF = Cohesive Failure
 MM = Mixed (Mode of AF and CF)
 AF = Adhesive Failure

Typical Rate of Strength Build-Up

Note: The following technical information and data should be considered representative or typical only and should not be used for specification purposes.

Overlap Shear Strength (psi), tested @ 73°F (23°C) at various times after bonding.

Condition	Scotch-Weld DP810	Scotch-Weld DP810 NS
10 minutes	50	500
20 minutes	1500	1750
1 hour	2250	2850
2 hours	2750	3350
4 hours	2950	3700
8 hours	3350	3850
24 hours	3600	4000

Scotch-Weld™

Low-Odor Acrylic Adhesives

DP810 • DP810 NS

Handling/Curing Information

Directions for use:

Apply adhesive to clean, dry substrates, which are free of paint, oxide films, oils, dust, mold release agents and all other surface contaminants. See surface preparation section for specific substrate preparation method.

50 ml cartridge:

Place duo-pak cartridge in 3M™ EPX™ Applicator. Remove cap. Dispense and discard a small amount of adhesive to assure even ratio and free flow. Clear orifice if necessary. Attach mixing nozzle. Apply adhesive to clean surfaces, join parts, secure until adhesive sets [15 minutes @ 70°F (21°C)].

Adhesive will fully cure in 8-24 hours @ 70°F (21°C). Store unused adhesive at 40°F (4°C) or below.

200/400 ml cartridge

While holding duo-pak cartridge in an upright position, remove and discard the insert from the cartridge by unscrewing plastic nut and removing metal washer. Place cartridge in a 1:1 200/400 ml EPX applicator. Dispense and discard a small amount of adhesive to ensure even ratio and free flow. Attach mixing nozzle and secure with plastic retaining nut. Apply adhesive to clean surfaces, join parts, secure until adhesive sets [15 minutes at 70°F (21°C)]. Adhesive will fully cure in 8-24 hours @ 70°F (21°C). Store unused adhesive at 40°F (4°C) or below.

Bulk Container Directions:

Follow manufacturer’s directions for bulk dispensing equipment.

Clean-up:

Excess adhesive can be removed with solvent such as 3M™ Scotch-Grip™ Solvent No. 3 or equivalent. Edge tack on a finished part or bond line can be removed with isopropyl alcohol*.

***Note:** When using solvents, extinguish all ignition sources and follow the manufacturer’s precautions and directions for use.

Approximate Coverage – By Size of Container

Bead Size	Linear ft per 50 ml	Linear ft per 200 ml	Linear ft per 400 ml	Linear ft per mixed gallon
1/2"	2.5	10	21	196
3/8"	4.5	18	37	350
1/4"	10.5	41	83	785
1/8"	41.5	165	331	3,130
1/16"	165	656	1,313	12,420

Square ft per 50 ml	Square ft per 200 ml	Square ft per 400 ml	Square ft per mixed gallon
5.2	20.8	41.6	400

Coverage in square feet – (.004" bond line)

Scotch-Weld™

Low-Odor Acrylic Adhesives

DP810 • DP810 NS

Surface Preparation

3M™ Scotch-Weld™ Low-Odor Acrylic Adhesives DP810 and DP810 NS can bond oily metal, plastic and other substrates with very little surface preparation. However, for the most consistent results and environmental resistance, all substrates should be clean, dry and free of paint, oxide films, dust, mold release agents and all other surface contaminants. The amount of surface preparation directly depends on the bond strength and environmental resistance desired by the user.

The following cleaning methods are suggested for common surfaces.

Steel and Aluminum

- 1) Wipe free of dust with oil-free solvent such as acetone or isopropyl alcohol.
- 2) Sandblast or abrade using clean fine grit abrasives (180 grit or finer).
- 3) Wipe again with solvent to remove loose particles.
- 4) If a primer is used, it should be applied within 4 hours after surface preparation. If 3M™ Scotch-Weld™ Structural Adhesive Primer 1945 B/A is used, apply a thin coating (.0005") on the metal surfaces to be bonded, air dry at 75°F (24°C) for 1 hr, then cure for 30 minutes at 180°F (82°C), 5 minutes at 250°F (122°C) or 3 hours at 75°F (24°C).

Note: Aluminum may also be acid etched. Follow the manufacturer's precautions and directions for this procedure.

Plastic/Rubber

- 1) Wipe with isopropyl alcohol.*
- 2) Abrade using fine grit abrasives (180 grit or finer).
- 3) Remove residue by wiping again with isopropyl alcohol.*

Glass

- 1) Solvent wipe surface using acetone.*
- 2) Apply a thin coating (0.0001" or less) of 3M™ Scotch-Weld™ Metal Primer EC-3901 to the glass surfaces to be bonded and allow the primer to dry a minimum of 30 minutes at 75°F (24°C) before bonding for maximum adhesion.
- 3) Remove residue by wiping again with isopropyl alcohol.*

***Note:** When using solvents, extinguish all ignition sources, including pilot lights, and follow the manufacturer's precautions and directions for use.

Scotch-Weld™

Low-Odor Acrylic Adhesives

DP810 • DP810 NS

Storage For maximum shelf life, store duo-pak cartridges and bulk containers at 40°F (4°C) or below. Store bulk containers at 40°F (4°C) or below.

Shelf Life When stored at the recommended temperatures in the original unopened containers, this product has a shelf life of twelve months from date of manufacture.

Precautionary Information Refer to Product Label and Material Safety Data Sheet for health and safety information before using this product. For additional health and safety information, call 1-800-364-3577 or (651) 737-6501.

Product Use All statements, technical information and recommendations contained in this document are based upon tests or experience that 3M believes are reliable. However, many factors beyond 3M's control can affect the use and performance of a 3M product in a particular application, including the conditions under which the product is used and the time and environmental conditions in which the product is expected to perform. Since these factors are uniquely within the user's knowledge and control, it is essential that the user evaluate the 3M product to determine whether it is fit for a particular purpose and suitable for the user's method of application.

Warranty and Limited Remedy Unless stated otherwise in 3M's product literature, packaging inserts or product packaging for individual products, 3M warrants that each 3M product meets the applicable specifications at the time 3M ships the product. Individual products may have additional or different warranties as stated on product literature, package inserts or product packages. 3M MAKES NO OTHER WARRANTIES, EXPRESS OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE OR ANY IMPLIED WARRANTY ARISING OUT OF A COURSE OF DEALING, CUSTOM OR USAGE OF TRADE. User is responsible for determining whether the 3M product is fit for a particular purpose and suitable for user's application. If the 3M product is defective within the warranty period, your exclusive remedy and 3M's and seller's sole obligation will be, at 3M's option, to replace the product or refund the purchase price.

Limitation of Liability Except where prohibited by law, 3M and seller will not be liable for any loss or damage arising from the 3M product, whether direct, indirect, special, incidental or consequential, regardless of the legal theory asserted, including warranty, contract, negligence or strict liability.



Industrial Business
Industrial Adhesives and Tapes Division
3M Center, Building 21-1W-10, 900 Bush Avenue
St. Paul, MN 55144-1000
800-362-3550 • 877-369-2923 (fax)
www.3M.com/industrial



Recycled Paper
40% pre-consumer
10% post-consumer

Printed in U.S.A.
©3M 2004 78-6900-9991-2 (6/04)