3M Optically Clear Laminating Adhesives 8141 • 8142

Product Description	8141	1.0 mil (25 micron) optically clear laminating adhesive for bonding smooth transparent substrates.
	8142	2.0 mil (50 micron) optically clear laminating adhesive for bonding smooth or textured transparent substrates.
Features		n room coating process eliminates common adhesive defects (e.g., no bubbles or gels).
		% light transmission (when corrected for reflection losses) and haze level unde 6 for crystal clear transparency.
	Ũ	n temperature, humidity and UV light resistance for long-term durable ications.
		polyester film liners for optimum adhesive smoothness and release acteristics.
	• Wou	and on plastic cores to minimize potential lamination defects.
	• Pres	sure-sensitive adhesive for manufacturing simplicity and economics.
	• Isoti	opic adhesive, without a film carrier, will not cause birefringence.

Construction	Products	8141 Adhesive	8142 Adhesive
	Adhesive Type:	2000MP Acrylic	2000MP Acrylic
	Adhesive Carrier:	None	None
	Release Liners:	Clear Polyester	Clear Polyester
	Approximate Thickness:		
	Release Liner	2 mils (50 microns)	2 mils (50 microns)
	Adhesive	1 mil (25 microns)	2 mils (50 microns)
	Release Liner	2 mils (50 microns)	2 mils (50 microns)

Optically Clear Laminating Adhesives

8141 • 8142

Application Ideas	• Touch screens – for bonding film and glass laminates.									
	• Transparent graphic overlays.									
	• Optical management fil	ms.								
Typical Physical Properties and Performance Characteristics	 Note: The following technical information and data should be considered representative or typical only and should not be used for specification purposes. Refractive Index: 1.471 Peel Adhesion: (90° peel, 12 in./min. 305 mm/min. 2 mil polyester to various surfaces) 									
								Substrate	8141 Adhesive	8142 Adhesive
							Initial (20 minute dwell)	Glass	22 oz/in (24 N/100 mm)	38 oz/in (42 N/100 mm)
		Polycarbonate	38 oz/in (42 N/100 mm)	51 oz/in (56 N/100 mm)						
		Acrylic	42 oz/in (46 N/100 mm)	56 oz/in (61 N/100 mm)						
	72 Hr Room Temperature	Glass	26 oz/in (28 N/100 mm)	32 oz/in (35 N/100 mm)						
		Polycarbonate	42 oz/in (46 N/100 mm)	59 oz/in (65 N/100 mm)						
		Acrylic	46 oz/in (50 N/100 mm)	63 oz/in (69 N/100 mm)						
	Ultimate Bond 72 Hr dwell at 158°F	Glass	30 oz/in (33 N/100 mm)	49 oz/in (54 N/100 mm)						
		Polycarbonate	34 oz/in (37 N/100 mm)	48 oz/in (53 N/100 mm)						
		Acrylic	38 oz/in (42 N/100 mm)	61 oz/in (67 N/100 mm)						

Processing

• Laminating –

Recommended nip roll or roller platen press type laminator to maintain optical aesthetics when laminated. Hand lamination not advised. Use best process control standards possible to control variables. (See **3M Laminating Technical Bulletin** for additional information.)

Die-cutting –

Use high precision, tight tolerance tooling designed to cleanly cut film and pressure-sensitive adhesive.

Optically Clear Laminating Adhesives 8141 • 8142

Application Techniques	For maximum bond strength the surface should be thoroughly cleaned and dried. To obtain greatest benefit, laminations should be done in the cleanest environment possible with static charge elimination.		
	Bond strength can be improved with firm application pressure and moderate heat causing the adhesive to develop intimate contact with the bonding surface.		
Environmental Performance	The properties defined are based on the attachment of impervious faceplate materials (such as aluminum) to an aluminum test surface.		
	Bond build-up – The bond strength of #2000MP High-performance Acrylic Adhesive increases as a function of time, temperature and humidity.		
	Temperature/humidity cycling – Polyester and glass lamination completes ten 24-hour cycles of modified Mil. Std. 202F, Method 106F (23°C-65°C, 95% R.H.) with no visual defects (i.e., bubbles, delamination, blistering, etc.).		
Shelf Life	Product retains its performance and properties for two years from date of manufacture if properly stored at room temperature conditions of 72°F (22°C) and 50% R.H. Storage in plastic bag is recommended.		

Optically Clear Laminating Adhesives 8141 • 8142

For Additional Information	To request additional product information or to arrange for sales assistance, call toll free 1-800-362-3550. Address correspondence to: 3M Bonding Systems Division, 3M Center, Building 220-7W-03, St. Paul, MN 55144-1000. Our fax number is 612-733-9175. In Canada, phone: 1-800-364-3577. In Puerto Rico, phone: 1-809-750-3000. In Mexico, phone: 5-728-2180.
Important Notice	3M MAKES NO WARRANTIES, EXPRESS OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. User is responsible for determining whether the 3M product is fit for a particular purpose and suitable for user's method of application. Please remember that many factors can affect the use and performance of a 3M product in a particular application. The materials to be bonded with the product, the surface preparation of those materials, the product selected for use, the conditions in which the product is used, and the time and environmental conditions in which the product is expected to perform are among the many factors that can affect the use and performance of a 3M product. Given the variety of factors that can affect the use and performance of a 3M product, some of which are uniquely within the user's knowledge and control, it is essential that the user evaluate the 3M product to determine whether it is fit for a particular purpose and suitable for the user's method of application.
Limitation of Remedies and Liability	If the 3M product is proved to be defective, THE EXCLUSIVE REMEDY, AT 3M'S OPTION, SHALL BE TO REFUND THE PURCHASE PRICE OF OR TO REPAIR OR REPLACE THE DEFECTIVE 3M PRODUCT. 3M shall not otherwise be liable for loss or damages, whether direct, indirect, special, incidental, or consequential, regardless of the legal theory asserted, including negligence, warranty, or strict liability.



Bonding Systems Division 3M Center, Building 220-7E-01 St. Paul, MN 55144-1000