



TEST REPORT

Applicant : 3M KOREA Ltd.
Address : Yoido P.O Box 93
Seoul, Korea

Page: 1 of 5

Report No. RT13R-U0055-E

Date: Jan. 11, 2013

Sample Description : The following submitted sample(s) said to be:-

Name/Type of Product : 3M High Performance Acrylic Adhesive
Item No. : 9197(S), 9198(S), 9199(S)
Sample ID No. : RT13R-U0055
Manufacturer/Vender : 3M KOREA Ltd.

Sample received : Jan. 08, 2013
Testing Date : Jan. 08, 2013 ~ Jan. 11, 2013

Test Method(s) : Please see the following page(s).
Test Result(s) : Please see the following page(s).

* Note 1 : The test results presented in this report relate only to the object tested.

* Note 2 : This report shall not be reproduced except in full without the written approval of the testing laboratory.

* Note 3 : The item no. is assigned by client and indicated according to their requirement and guarantee letter.

Approved by,

E.Y.Lee / Lab. Technical Manager

Authorized by,

H.W.Yoo / Lab. General Manager

This Test Report is issued by the Company subject to its Terms and Conditions of Business printed overleaf. Attention is drawn to the limitations of liability, indemnification and jurisdictional issues defined therein. This Test Report shall not be reproduced, except in full, without prior written consent of the Company.

Intertek Testing Services Korea Ltd.

Seoul Office: Tel : 02-6090-9500 Fax : 02-3409-0026 Daegu Office : Tel : 053-600-8647 Fax : 053-600-8645 Web Site : www.Intertek.co.kr
Seoul Lab. Address : 1/F, A-ju Digital Tower, #284-56, Seongsu 2-ga, Seongdong-Gu, Seoul, 133-833 Korea
Ulsan Lab. Address : #340-2, Yongam-Ri, Chongryang-Myun, Ulju-Gun, Ulsan 689-865 Korea



TEST REPORT

Page: 2 of 5
Date: Jan. 11, 2013

Report No. RT13R-U0055-E

Sample ID No. : RT13R-U0055

Sample Description : 3M High Performance Acrylic Adhesive

Test Item	Unit	Test Method	MDL	Result
Antimony (Sb)	mg/kg	With reference to US EPA 3052, by acid digestion and determined by ICP-OES	2	30
Phthalates				
Dibutyl phthalate (DBP)	mg/kg	With reference to US EPA 8061A, by solvent extraction and determined by GC/MS	50	N.D.
Di(2-ethylhexyl) phthalate (DEHP)	mg/kg	With reference to US EPA 8061A, by solvent extraction and determined by GC/MS	50	N.D.
Di-n-octyl phthalate (DNOP)	mg/kg	With reference to US EPA 8061A, by solvent extraction and determined by GC/MS	50	N.D.
Diisononyl phthalate * (DINP)	mg/kg	With reference to US EPA 8061A, by solvent extraction and determined by GC/MS	100	N.D.
Diisodecyl phthalate ** (DIDP)	mg/kg	With reference to US EPA 8061A, by solvent extraction and determined by GC/MS	100	N.D.
Benzyl butyl phthalate (BBP)	mg/kg	With reference to US EPA 8061A, by solvent extraction and determined by GC/MS	50	N.D.
Diisobutyl phthalate (DIBP)	mg/kg	With reference to US EPA 8061A, by solvent extraction and determined by GC/MS	50	N.D.

Tested by : YK Cho, MB Song

Notes : mg/kg = ppm = parts per million
< = Less than
N.D. = Not detected (<MDL)
MDL = Method detection limit

* DINP include two types of phthalate (CAS No. 68515-48-0 and 28553-12-0).

** DIDP include two types of phthalate (CAS No. 68515-49-1 and 26761-40-0).

This Test Report is issued by the Company subject to its Terms and Conditions of Business printed overleaf. Attention is drawn to the limitations of liability, indemnification and jurisdictional issues defined therein. This Test Report shall not be reproduced, except in full, without prior written consent of the Company.

Intertek Testing Services Korea Ltd.

Seoul Office: Tel : 02-6090-9500 Fax : 02-3409-0026 Daegu Office : Tel : 053-600-8647 Fax : 053-600-8645 Web Site : www.Intertek.co.kr
Seoul Lab. Address : 1/F, A-ju Digital Tower, #284-56, Seongsu 2-ga, Seongdong-Gu, Seoul, 133-833 Korea
Ulsan Lab. Address : #340-2, Yongam-Ri, Chongryang-Myun, Ulju-Gun, Ulsan 689-865 Korea

TEST REPORT

Report No. RT13R-U0055-E

Sample ID No. : RT13R-U0055

Sample Description : 3M High Performance Acrylic Adhesive

* View of sample as received;-



This Test Report is issued by the Company subject to its Terms and Conditions of Business printed overleaf. Attention is drawn to the limitations of liability, indemnification and jurisdictional issues defined therein. This Test Report shall not be reproduced, except in full, without prior written consent of the Company.

Intertek Testing Services Korea Ltd.

Seoul Office: Tel : 02-6090-9500 Fax : 02-3409-0026 Daegu Office : Tel : 053-600-8647 Fax : 053-600-8645 Web Site : www.Intertek.co.kr

Seoul Lab. Address : 1/F, A-ju Digital Tower, #284-56, Seongsu 2-ga, Seongdong-Gu, Seoul, 133-833 Korea

Ulsan Lab. Address : #340-2, Yongam-Ri, Chongryang-Myun, Ulju-Gun, Ulsan 689-865 Korea


TEST REPORT

Report No. RT13R-U0055-E

Sample ID No. : RT13R-U0055

Sample Description : 3M High Performance Acrylic Adhesive

Flow Chart (Metal Testing)



** Remarks : The samples were dissolved totally by pre-conditioning method according to above flow chart.

This Test Report is issued by the Company subject to its Terms and Conditions of Business printed overleaf. Attention is drawn to the limitations of liability, indemnification and jurisdictional issues defined therein. This Test Report shall not be reproduced, except in full, without prior written consent of the Company.

Intertek Testing Services Korea Ltd.

Seoul Office: Tel : 02-6090-9500 Fax : 02-3409-0026 Daegu Office : Tel : 053-600-8647 Fax : 053-600-8645 Web Site : www.intertek.co.kr

Seoul Lab. Address : 1/F, A-ju Digital Tower, #284-56, Seongsu 2-ga, Seongdong-Gu, Seoul, 133-833 Korea

Ulsan Lab. Address : #340-2, Yongam-Ri, Chongryang-Myun, Ulju-Gun, Ulsan 689-865 Korea



TEST REPORT


Page: 5 of 5
Date: Jan. 11, 2013

Report No. RT13R-U0055-E

Sample ID No. : RT13R-U0055

Sample Description : 3M High Performance Acrylic Adhesive

Flow Chart (Phthalates)



***** End of Report *****

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct.

This Test Report is issued by the Company subject to its Terms and Conditions of Business printed overleaf. Attention is drawn to the limitations of liability, indemnification and jurisdictional issues defined therein. This Test Report shall not be reproduced, except in full, without prior written consent of the Company.

Intertek Testing Services Korea Ltd.

Seoul Office: Tel : 02-6090-9500 Fax : 02-3409-0026 Daegu Office : Tel : 053-600-8647 Fax : 053-600-8645 Web Site : www.Intertek.co.kr

Seoul Lab. Address : 1/F, A-ju Digital Tower, #284-56, Seongsu 2-ga, Seongdong-Gu, Seoul, 133-833 Korea

Ulsan Lab. Address : #340-2, Yongam-Ri, Chongryang-Myun, Ulsan 689-865 Korea